

Houston Fire Department

Four Leaf Tower Report



Fire Chief Chris Connealy

Prepared By
Assistant Chief Little, Assistant Chief Smith, Assistant Chief Trevino
Assistant Chief Sims, Fire Alarm Dispatcher M. Herman

<http://www.houstonfire.org>

Four Leaf Tower Report

Acknowledgments	1
Introduction	2
Summary	3 - 18
Recommendations and Discussions.....	19 - 39
Conclusion.....	40

A Note About This Report

This version of the report does not include the picture, diagrams, or exhibits that are referred to throughout it. If you have any further questions about this version please contact Alicia Whitehead of the Houston Fire Departments Public Information Office at (713) 865-4513 or alicia.whitehead@cityofhouston.net

ACKNOWLEDGMENTS

The Houston Fire Department must take a hard look into the future and contemplate substantial changes because of the events of September 11, 2001, and the recent Four Leaf Towers fire. It has been said: "The only thing man learns from history is that he does not learn." I believe that this department and all of its members will learn from these incidents.

The Department endured a difficult time after it suffered the loss of one of its own, Captain Jay Jahnke. Even with the loss of Captain Jahnke, the Four Leaf Towers fire is indicative of what the Department does best - - fights fires and saves lives. In spite of their personal loss, the firefighters responding to the four Leaf Towers fire continued diligently evacuating residents of the building. Hundreds were saved due to their hard work and courage. The objective of this report is to help make the Houston Fire Department a better fire department.

I would like to thank all the individuals involved in generating this report. They worked tirelessly to complete this report. Their professionalism is a credit to this great city.

Special thanks go to: Houston Fire Department Command Team, Houston Fire Department Arson Division, Houston Fire Department Communications Division, Joint Labor Management Safety Committee, firefighters who responded to the incident, local Houston media, Four Leaf Towers Management, and Larry Stevens.

Chris Connealy
Fire Chief

INTRODUCTION

On the morning of October 13, 2001, the Houston Fire Department responded to a report of smoke and fire on the fifth floor of the Four Leaf Towers, a highrise apartment building located at 5110 San Felipe in Houston, Texas. The Four Leaf Towers west building is a 41-story highrise apartment building. The building consists of 400 units ranging from 1,015 to 4,990 square feet. The west tower has a total square footage of 814,624 square feet.

The following report is a summary of the events that occurred that morning. It must be reiterated that this report will serve as a tool to improve the Department. It is not the intent of this report to place blame on any individual, but rather to fully understand what happened during this incident, correct any deficiencies, and make recommendations to help prevent other similar events from occurring.

Often tragedies are the results of multiple factors. Often it is impossible to say with any certainty that changing any particular factor would change the outcome. Our goal in producing this internal report is to outline a variety of factors that came to light from this investigation. It is extremely important that the Department learns from this incident and that we work together to prevent similar incidents in the future. Firefighting is a very dangerous profession. Nevertheless, this never excuses all stakeholders from working aggressively to minimize those risks. Our firefighters and community deserve nothing less.

SUMMARY

On Saturday, October 13, 2001 at 04:43:36, an initial call from Four Leaf Towers was received by the Houston City Neutral (911). At 04:43:47 the call was transferred to the Department's Communications Division. The caller reported the smell of smoke in the Four Leaf Towers, a highrise apartment building. See diagram A and photograph # 1. The information was taken and the call was queued for dispatch with a highrise response at 04:46:19. At 04:46:19, a second call was received by the Communications Division. A third call was received at 04:47:31. Both callers reported smoke on the fifth floor. At 04:48:48 the appropriate stations were alerted. The dispatch sequence of apparatus, given two consecutive times, was: District 28, 6, 5; Engine 2, 28, 3, 38, 11; Ladders 28, 38, 301; Safety 2, 15; Ambulance 28. The dispatcher stated: "Smoke on the fifth floor, 5100 San Felipe Road near South Post Oak Lane, the Four Leaf Towers on the fifth floor, the east tower."

Dispatched apparatus began acknowledging the alarm and responding. At 04:51:39, a caller notified dispatch that there is an actual fire at the Four Leaf Towers. At 04:52:53 dispatch notifies all responding companies that they are receiving multiple calls of fire on the fifth floor. Engine 2 was the first on location; it reported heavy fire coming from the exterior of the building. See photograph #2. E-2 requested a second alarm. As other apparatus arrived, E-2's crew advanced to the fifth floor by utilizing stairwell B. They were escorted by the building engineer. See photograph #3.

The crew of E-2 took equipment to the fifth floor. The crew was assisted by the driver of E-2. Safety-2 arrived at 04:54:02. Arriving companies were written down for the first arriving district chief who was District 28. He arrived at 04:54:22. Immediately D-28 established his command and began implementing the Department's highrise procedure. At 04:55:39, Engine 28 was the second engine to arrive. It was ordered by D-28 to establish lobby control in accordance with the highrise guidelines. See diagram B and photograph #4.

E-2 arrived on the fifth floor from stairwell B on the west side of the building and entered to the right on the fire floor. The firefighter on E-2 and the driver on E-2 connect the fire hose they brought with them to the hose connection located in the hose cabinet on the fifth floor. See photograph # 5. This hose cabinet is about thirteen feet from stairwell B and about thirty-one feet from the involved apartment on the west side of the building. The captain on E-2 begins checking for residents on the west side of the building. He went from apartment to apartment knocking on doors. E-2 captain then entered a service area. He checked the service entrance doors for apartments fifty-two and fifty-three.

E-2 firefighter stretched out the fire hose from the hose cabinet. The hose is stretched into the elevator lobby area making a loop and back out into the hall toward the door of apartment fifty-two. E-2 firefighter knelt at the door, he opened the nozzle spraying some water while letting the air out of the line. E-2 firefighter then cracked open the door. He quickly closed the door, because heavy smoke rushed out. At 05:01:02 the E-2 captain

tells command: "E-2, we've got the hose laid. We're waiting on another company on the fifth floor."

Ladder 28 arrived at 04:56:23. It was the first ladder at the location. The involved floor was difficult to discern because of the design of the building. Lobby control told the captain of L-28 that the fire was on the third floor instead of the fifth floor. Nevertheless, an employee of the highrise had previously told this captain that the fire was on the fifth floor. The L-28 captain and his firefighter took an elevator to the fourth floor. Subsequently, they went to the fifth floor via stairwell B.

The third engine to arrive is E-3. It arrives at 04:55:57. It is on location by mast-mobile automatic status terminal. In accordance with the request of E-2, at 04:56:34, the dispatcher gave a second alarm. The appropriate stations were alerted. The dispatch sequence of apparatus, given two consecutive times, was as follows: District 69, 21, 10; Engine 16, 60, 37, 51; Ladder 16, 51, 69; Rescue 11; Cascade 2; Rehab 17; Senior 2; Squad 3.

Because E-28 had established lobby control, it did not need a firefighter. Therefore, when E-3 arrived it was given this firefighter. With this addition E-3 had a crew of four firefighters - - one captain and three firefighters. The E/O - - the driver- - remained with the apparatus in order to connect the apparatus to the building's stand pipe system located at the southwest corner of the property. See diagram C and photograph #6. Safety-2 mistakenly told the E-3 crew that the fire was on the third floor. The crew attempted to get to the third

floor by utilizing stairwell B. The entrance is located at the west side exterior of the building. These doors were locked. E-3 returns to the lobby and attempted to use an elevator. A firefighter controlled the elevators. An elevator was given to E-3 who took it to the second floor. This floor is used for storage and is non-residential. See diagram D and photograph #7. E-3 attempted to gain access to stairwell B from the second floor. The stairwell door was locked. Subsequently, E-3 accompanied a resident down to the lobby via elevator. Nevertheless, E-3 did not notify command of its delay.

At 05:00:22 and at 05:00:54, command attempted to contact E-3. At both times there was no response. Meanwhile, E-3 had left the building through its west side. In order to determine the fire floor, E-3 looks at the tower. See photograph #8. The doors to stairwell B were subsequently unlocked and propped open. Via that stairwell, E-3 reached the third floor. Enroute to that floor the crew was hampered by residents using the stairwell to leave the building. At 05:01:13, command attempted to transmit to E-3 as follows: "E-3, is E-3 already on the fire floor?"¹ There is no immediate response from E-3. Nevertheless, E-2 responded by stating as follows: "Engine 2, I am on the fire floor, up on five!" This response was at 05:01:18.

At 05:02:54, E-2 asked command as follows: "E-2, where is my second company?" At 05:03:02 command's response was: "E-2 you ought to have E-3 up there backing you up." Subsequently, E-2 responded as follows: "I am trying to primary search all these rooms

¹It is believed command is meant to say: "E-2, is E-3 already on the fire floor?" Command's communication, as were all the transmitted communications in this report, was taken directly from the dispatch communication tape of the 6-11 Four Leaf fire.

so I can get in there. I am waiting for another company.” With their regulators operating, E-2 captain and his firefighter forced open the door to apartment fifty-one.

They found no one in the apartment; they quickly left. They disconnected their regulators.

Subsequently, the E-2 firefighter stated that the fire floor was smoky. Nevertheless, command was not notified of this condition.

At 05:03:17 command finally contacted E-3. At 05:03:25, E-3 was asked: “Are you on five to back up E-2?” The response of E-3 was neither recorded nor heard by the dispatcher.

Nevertheless, it is believed that E-3’s radio was on channel D while all other companies were operating on Channel A. Command then told E-3: “You need to get up there to back up E-3, so they can try to knock this thing down. It looks like it is starting to spread.”

²There is no recorded response from E-3.

A thermal imager was never on the fire floor. Therefore, crews on the fire floor were denied this advantage. At 05:04:00, L-28 arrived on the fifth floor - - the fire floor. The crew proceeded north down the hallway to apartment fifty-two which is located at the end of a narrow corridor. See diagram E and photograph #9. One of the L-28 firefighters asked the E-2 driver to retrieve a thermal imager. The driver left the fire floor in order to comply with the request. He retrieved the thermal imager; he attempted to return to the fire floor via stairwell B. Nevertheless, he is unable to get there because the stairwell was filled with

²It is believed that command was telling E3 to back up E-2.

smoke. Subsequently, he gave the imager to another crew going up. The location of the imager cannot be ascertained after this exchange.

At approximately 04:59, the weather conditions began to change. The wind began to blow from the north at over seventeen knots. The strong wind blew heat and smoke back into the building. This caused the fire to spread to the bathroom and bedroom of apartment fifty-two. See photograph #10.

Subsequently, entry was made into apartment fifty-two. See photograph #11. Heavy smoke billowed out when an E-2 firefighter opened the door of the apartment. The door was quickly closed. After turning on their regulators, the two crews crouched at the door of the apartment. The E-2 captain and E-2 firefighter opened the door and entered the apartment while the L-28 captain and firefighter remained at the door. Entry was made with the E-2 firefighter on the nozzle. The men entered the foyer area. See diagram F and photograph #12. Because of the heavy smoke, the team could not see the fire. They, however, felt the heat. The E-2 crew returned to the door.

The L-28 captain and firefighter remained waiting at the door. Subsequently, the E-2 captain and the L-28 captain moved down a short hallway where the smoke was thicker.

The former searches the kitchen while the latter remained still. Because of a lack of a thermal imager, the two captains are unable to determine the seat of the fire. The E-2 captain told his L-28 counterpart that he does not want the fire to get between the team and the exit.

Only with an open nozzle was the E-2 firefighter able to knock down the fire. Each time the nozzle was closed the fire re-appeared. The nozzle was utilized in a semi-fog pattern in an attempt to keep the team cool. The E-2 captain told his counterpart that if they stayed in their present location, they would be trapped. The E-2 captain expressed confusion to his counterpart regarding the location of the exit from the apartment. Shortly afterwards, the windows in the bedroom on the west side of the building were blown out. As a result, more heat and smoke filled the fire floor.

Approximately three minutes have elapsed since the windows were blown out. The E-2 firefighter closed his nozzle; handed it to the L-28 captain. He explained to this captain that he is running out of air and that he needs to get out. The E-2 firefighter twice asked this captain as follows: "You have got E-2 captain, right?" After an affirmative response from the L-28 captain, E-2 firefighter leaves the apartment. The L-28 firefighter volunteers to take the E-2 firefighter to the stairwell. According to the L-28 captain, the E-2 firefighter was excited and anxious about leaving the fire floor. The integrity of the crews was now disrupted.

The two firefighters were separated while crawling toward the stairwell. E-2 firefighter continues to follow the looping hose into the elevator lobby and into the hall. When he reached the exit, he had run out of air after only four to five minutes of intermittent air pack use. After reuniting with E-2 firefighter at stairwell B, L-28 firefighter escorted him into the stairwell. See photograph #14. While E-2 firefighter continued down the stairs, his L-28 counterpart attempted to return to apartment fifty-two. As he was moving down the hall,

his vibe-alert warned him of low air. He also had run out of air after only five to six minutes of intermittent air pack use. He immediately returned to the stairwell B; he left the fire floor. Both firefighters have now left the fire floor and have not notified command about leaving L-28 captain and E-2 captain on the fire floor without back up.

The E-2 and L-28 captains were in the foyer of the apartment four minutes after entry. See photograph #15. The E-2 captain was Captain Jay Jahnke, the decedent. Therefore, except for radio transmissions, others must be relied upon to present subsequent events involving the decedent. According to L-28 captain, the decedent became concerned about the possibility of a low volume of air in his air bottle. They agreed to leave the fire floor together. The L-28 captain told his counterpart: "Hold on I will go with you." They left the apartment and followed the hose. The E-2 captain came to a pile of hose after a short distance. The decedent became disoriented and confused as to the direction that he should have been going. See photograph #16.

There is still confusion among firefighters as to the location of the fire floor. Lobby command sent L-38 to a floor above the fire. At 05:07:01, L-38 transmitted as follows: "The fire is on floor three." While confusion as to the location of the fire floor continued, L-28 was unable to see anything on the fire floor. The situation was exacerbated because heat and smoke continued to billow out of the apartment. The self-closing door did not shut because the hose was left inside the door. At 05:09:02, lobby control asked L-28 captain for a progress report. There was no response to this request. L-28 captain had put down

his radio and hand light while feeling for the hose. He believed that E-2 captain was following him.

At 05:09:45, units at the location were: E-2, 28, 03, 38, 51, 60; L-28, 38, 301, 51; R-11; Safety 2, 15; D-28, 06, 05, 69, 21; Amb-28; EMS - Senior 2; Cascade-2. This was approximately nine minutes after the crews of E-2 and L-28 entered apartment fifty-two.

Subsequently, the L-28 captain and his E-2 counterpart were reunited. The L-28 captain described his counterpart as “confused and excited.” He told Captain Jahnke as follows: “Calm down, we just need to follow the hose to the hose cabinet and the exit will be 15 feet further.” The two men came to a second pile of hose. While L-28 captain began feeling for the hose leading to the hose cabinet, the two men became separated. At 05:09:51, Captain Jahnke transmitted a call for help. He stated: “E-2, we’re trapped on the fifth floor! E-2, help!” The L-28 captain is unaware of this transmission because he had left his radio and hand light at the entrance to apartment fifty-two. See photographs #17a, b and c.

The dispatcher does not hear a response to Jahnke’s call from command. Therefore, the dispatcher issued a MAY-DAY at 05:11:58. The dispatcher transmitted as follows: “All companies on San Felipe command, you’ve got a MAY-DAY on the sec [sic], on the fifth floor! MAY-DAY on the fifth floor! We’re sending you a 3-11.” Command acknowledged the transmission; it immediately began sending multiple companies to the lobby for assignment.

At 05:12:18, a third alarm was dispatched. The appropriate stations were alerted. On two consecutive times the dispatch sequence of apparatus was: Engine 5, 505, 33, 8; Ladder 6, 33; District 8; Communications Vehicle 11. At the time of the MAY-DAY call, E-3 was on the third floor of the highrise; it was attempting to connect hose to the standpipe in stairwell B. Visibility was poor because of smoke coming down from the fifth floor. Upon hearing the MAY-DAY, E-3 abandoned the standpipe and took the stairs to the fifth floor.

The conditions on the fire floor had deteriorated. See photograph #18 a, b and c. Visibility was zero. The heat had intensified; steam was now a factor on the fire floor. The steam was caused by two discharging fire sprinklers in the hall. Finally, L-28 captain found the hose going to the cabinet. He yelled to Captain Jahnke as follows: "I found the hose cabinet and the exit is this way." He then moved to stairwell B. See photograph #19. L-28 captain and Jahnke were now separated. Neither knew the location of the other. At 05:12:18, Jahnke transmitted: "E-2, we're trapped on the fifth floor." After making his way to the main elevator lobby, Jahnke made his last call for help. He stated: "E-2, emergency! We're running out of air." Subsequently, he collapsed in front of elevator one. See photograph #20. According to these radio transmissions, Jahnke must have thought that L-28 captain was still on the fire floor with him. Nevertheless, L-28 Captain had entered the vestibule of stairwell B and then lost consciousness. See photograph #21. Approximately nine minutes had passed since the crews of E-2 and L-28 first entered apartment fifty-two.

At 05:15:30, a fourth alarm was requested and dispatched. The appropriate stations were alerted. On two consecutive times the dispatch sequence of apparatus was: Engine 6, 49, 69, 13; Ladder 21, 68; District 31.

The E-3 crew reached the fifth floor after the MAY-DAY call. Nevertheless, they had to return to the first floor immediately because their vibe-alerts began sounding. There was confusion and traffic in stairwell B because of smoke and residents moving to the lobby.

The E-3 crew was separated and fragmented. Two of its firefighters were separated from the captain and a third firefighter. After exchanging air bottles, the captain and his firefighter returned to stairwell B. See photograph #22. This stairwell is smoky, but there were not any transmissions that notified command of this condition.

The remainder of the E-3 crew had difficulty returning to the fire floor because residents were coming down stairwell B. When the crew finally returned to the fifth floor, L-28 captain was found prone in the vestibule. See photograph #22. E-3 captain shook him and asked: "Who are you?" The L-28 captain responded as follows: "L-28 captain. E-2 captain is right behind me." The E-3 captain escorted his L-28 counterpart down a few stairs. When he returns, he and his firefighter must leave because their vibe-alerts began sounding. As they went down the stairwell, they assisted residents trying to escape from the building.

Rescue 11 had now been assigned to find the E-2 captain. The E-3 captain told the R-11 captain that the missing firefighter is “to the right on the fifth floor.” During this same time period, L-28 captain was being treated by EMS personnel outside of the building.

At 05:27:05 command acknowledged that the crew of L-28 is accounted for, but the E-2 captain still had not been located. E-60 was assigned to assist R-11 on the fifth floor. This crew encountered heavy smoke on the third floor. The captain ordered one of his firefighters to get air bottles for the crew. When he returned they locked in their regulators. Subsequently, they proceeded to the fifth floor.

The R-11 crew reached the fifth floor with its four-member crew intact. It entered the fire floor while attaching a tag line to the door. The R-11 captain crawled north on the left side of the hall. A firefighter from this crew crawled north on the right side of the hall. See photograph #24. Visibility was still zero, but heat was no longer a factor because sprinklers were discharging water. As they moved down the hall toward apartment fifty-two, a PASS device - - Personal Alert Safety System - was heard. The R-11 firefighters made contact with the E-2 Captain Jahnke, about four to five feet away from the wall. The firefighter informed his captain of this discovery. The captain subsequently moved away from the wall and made contact with Jahnke. See photograph #24. The decedent is found face down with his helmet and face piece removed. See photograph #25. Jahnke did not have a pulse. His air pack was empty. Subsequently, L-51 reached the fire floor. It met R-11 after following the previously established tag line.

Subsequently, the crew of E-60 entered the fire floor. After moving west along the wall, this crew heard other firefighters and the sound of a PASS device. It unknowingly moved toward apartment fifty-two. After being sprayed by water from an overhead sprinkler, the crew turned back about eight feet. It then encountered R-11 and L-51 with Captain Jahnke. The three crews tried to move Jahnke, but Jahnke's air pack kept hanging up on the carpet. Jahnke's air pack and gloves were removed. Nevertheless, it was still difficult to move him. A firefighter from E-60 attempted to leave the fire floor because he was running out of air. He was unsuccessful; he collapsed near the exit. No one notices his perilous situation because he did not have a partner. See photograph #26.

A fragmented E-3 crew - - a captain and firefighter - - reached the fifth floor landing again. Other firefighters were also on the landing. E-3 captain found a firefighter laying face down near the exit. He shook the firefighter and asked: "Are you E-2 [Jahnke] captain?" He was actually the E-60 firefighter who had recently collapsed. Nevertheless, E-3 captain believed that the firefighter had answered affirmatively. He was not aware that other crews had the E-2 captain about 18 feet away. The E-3 Captain pulled the firefighter up and escorted him to the first floor. After learning that he did not have the E-2 captain, he returned to the fifth floor. Nevertheless, his vibe-alert sounded. Therefore, he returned to the first floor with his one remaining firefighter. His two other firefighters were still missing.

Subsequently, D-5 reached the fire floor. The landing was congested because of the presence of the various crews. Because firefighters were not moving, the chief officer ordered firefighters to advance a line to find the missing firefighter. He was apprised that

the missing firefighter had been found. R-11, L-51, and E-60 had difficulty moving Jahnke because of congestion near the exit and the landing. The E-60 captain ran out of air and the congestion prevented him from getting to the exit. After removing his mask, he began coughing. He collapsed near the same spot where his firefighter had previously collapsed. Firefighters carried him down to the first floor.

While Jahnke was being moved to the stairwell, the doors to the fire floor and the stairwell landing were closed. Two members of R-11 were thereby separated from their crew. With the door closed behind them, these two members of R-11 attempted to find their way out by going into the service elevator area. See photograph #27. At 05:34:19, the transmission was: "R-11, we have two firefighters trapped." The separated firefighters searched the small confined area for an exit. The area was very confusing because it has several doors and an elevator.

At 05:36:24, Jahnke was taken to the first floor; he is treated by EMS personnel. A few minutes later, the two trapped firefighters from R-11 found an exit placard on the wall that showed the exit. See photograph #28. The firefighters safely returned to the first floor after finding the exit door. They rejoined their crew. At 05:41:07, all companies were ordered to the lobby; a personnel accountability report - - PAR - - was taken. Calls for help from residents continued from the upper floors. The incident remained in a rescue mode. The Department continued to remove residents. Several hundred civilians were rescued.

The fire was allowed to burn for 2 hours and 31 minutes. Eventually, fire task force crews were organized. At 07:14:50, the fire was attacked and knocked down while rescue efforts

continued. At 09:13:39, the fire was declared under control; a 7-1 was signaled tapping out the fire. Extensive damage was done to the fifth and sixth floors in the northwest corner of the building. See photographs # 29 and 30.

Alarms dispatched:

- 1st D-28, D-6, D-5, E-2, E-3, E-28, E-38, E-11, L-28, L-38, L-301,
Safety-2, 15, A-28 @ 04:48:15
- 2nd D-69, D-21, D-10, E-16, E-60, E-37, E-51, L-16, L51, Cascade-2, R-11,
Rehab-17, EMS Senior-2, Squad-3 @ 04:55:53
- 3rd D-8, -5, E-505, E-33, E-8, L-6, L-33, Communications Vehicle –11
Shift Commander –17 @ 05:11:53
- 4th D-31, E-6, E-49, E-69, E-13, L-21, L-68 @ 05:15:13
- 5th D-82, E-536, E-44, E-62, E-46, L-36, L-46 @ 05:47:26
- 6th Safety-23 @ 05:54:06
Cascade-30 @ 06:03:58
E-19, E-35 @ 06:08:25
L-31 @ 06:37:06

Ambulance Dispatched

A-28 @ 04:48:15	AS-002 @ 04:55:53	S-003 @ 04:55:53
S-62 @ 05:16:18	A-02 @ 05:16:18	A-62 @ 05:17:16
A-528 @ 05:18:17	AS-57 @ 05:28:00	A-11 @ 05:38:19
S-60 @ 05:38:19	A-60 @ 05:39:55	S-06 @ 05:38:19
A-37 @ 05:42:24	M-75 @ 05:42:25	A-33 @ 05:42:54
M-05 @ 06:58:30	AS-082 @ 09:45:52	

RECOMMENDATIONS AND DISCUSSION

RECOMMENDATION #1: THE DEPARTMENT SHOULD ENSURE THAT THE DEPARTMENT'S GUIDELINES AND PROCEDURES ARE FOLLOWED.

Discussion: During the incident in question, certain Department guidelines were not followed. Department guidelines mandate that crews remain intact. Crews should enter and exit together. Crews should stay together. Guidelines require that no firefighter should operate alone. Under the rules, if a problem occurs, the incident commander should be immediately notified. See 6.06 of the Department's *Highrise Firefighting Guideline*.

Crews should not use elevators in a highrise fire unless they can do so safely. See 6.01 A - 7 through 9. Under the Department guidelines, the elevators at the Four Leaf Tower should not have been utilized by firefighters. The fire floor was the fifth floor.

According to the guidelines, a Rapid Intervention Team - - RIT - - should have been created. The fifth engine company should become the initial RIT. See 6.01 F of the *Highrise Firefighting Guideline*. During the incident in question, E-11 was the fifth engine.

The factors that make the creation of a RIT imperative were present. There was a sudden wind change. There was a missing firefighter. Nevertheless, a RIT was never created.

The availability of manpower was not an issue in determining whether a RIT should have been created during the incident in question.

RECOMMENDATION #2: THE DEPARTMENT GUIDELINES SHOULD GIVE THE INCIDENT COMMANDER THE FLEXIBILITY TO USE VERBAL ASSIGNMENTS OF COMPANIES RATHER THAN AUTOMATIC ASSIGNMENTS AFTER FIRE HAS BEEN REPORTED BY THE INVESTIGATIVE TEAM.

Discussion: According to the Department's *Highrise Firefighting Guideline*, whenever fire has been reported by the investigative team, all first alarm companies should proceed to their automatic assignment positions. This was created to ensure that all tasks related to the incident were covered. The problem that arises is that the incident commander cannot always verify the status of the pre-assigned tasks. In order to ensure completion of all tasks, companies should advise the IC prior to beginning their automatic pre-assignments. The IC should have the flexibility to make assignments based upon the current situation.

Benchmark updates must be given throughout the incident. If for any reason the assignment cannot be carried out, the IC must be notified. Accountability on the fire ground is paramount to the success and safety of all responding members.

The Fire Administration has acquired a FEMA grant, with funding to be matched by the City of Houston, to purchase an improved personnel accountability system. A request for proposal is currently out. It will be purchased soon. This system will help to improve overall fire ground accountability. Nevertheless, officers must still keep their crews intact so the incident commander can maintain accountability for all personnel on the fire ground. The best accountability system in the world will not work well if officers do not keep their crews together. This fire nearly took the lives of five firefighters. The independent actions

of firefighters outside of the safe operating procedures of the Department nearly cost them their lives.

RECOMMENDATION #3: THE DEPARTMENT SHOULD DEVELOP AN ON-SCENE COMMUNICATIONS GUIDELINE THAT OUTLINES INFORMATION THAT MUST BE TRANSMITTED TO THE INCIDENT COMMANDER.

Discussion: During the incident, two firefighters left the fire floor without notifying command that only two firefighters remained on the fire floor and they were without back up. The City of Houston purchased 270 portable radios so that each firefighter would have a radio on the fire ground. This was recommended by NIOSH following the McDonald's fire in February 2000 that claimed the life of two Houston firefighters. All firefighters have portable radios while on duty. All members are responsible for keeping command informed of information. The firefighter on L-28 who could not return to his captain because of insufficient air should have notified his officer he was going downstairs. L-28 firefighter should have stayed with E-2 firefighter to avoid being alone.

RECOMMENDATION #4: THE DEPARTMENT SHOULD AUGMENT ITS HIGHRISE GUIDELINES TO ALLOW THE ASSIGNMENT OF ANOTHER COMPANY TO A TASK WHEN THE ORIGINALLY ASSIGNED COMPANY CANNOT COMPLETE A TASK AND/OR COMMAND IS UNABLE TO MAKE CONTACT WITH THE ORIGINAL COMPANY SHORTLY AFTER THE ASSIGNMENT WAS GIVEN.

Discussion: When Department dispatchers are unable to contact a dispatched EMS unit, another EMS unit is sent to the assignment. Supervisors are notified. We do not have analogous procedures for highrise fires. During the incident in question, at a crucial point, command could not make contact with E-3, the assigned backup unit for the fire floor. Had

such a procedure been in place, no one would have been left on the fire floor without backup. In addition, failure to respond to command could indicate a MAY-DAY situation.

RECOMMENDATION #5: THE DEPARTMENT SHOULD CONSIDER ANNUAL UPDATES TO ITS HIGHRISE PLANS. DISTRICT CHIEFS SHOULD SCHEDULE ANNUAL VISITS OF THE FIRST ALARM COMPANIES TO PRE-FIRE INSPECTIONS OF ALL HIGHRISE BUILDINGS IN THEIR TERRITORIES WITH AN EMPHASIS ON GETTING ALL THE COMPANIES FAMILIAR WITH BUILDING LAYOUTS AND SPECIAL PROBLEMS.

Discussion: The National Institute for Occupational Safety and Health finds in *Fatality Assessment and Control Evaluation Investigative Report #F2000-13*:

Pre-fire plans or inspections are excellent opportunities for fire departments to determine the following: age of structure, structural integrity, exposed interior in insulation materials, type of roof structure and supports (truss, bowstring, etc.), type of interior support structures, type of materials used in the structure (such as wood, steel, plastic, foam or materials that produce toxic gases when subject to heat), storage of flammable or toxic materials, amount of load (HVAC units, coolers, etc.), water supply, and automatic sprinkler systems. Pre-fire plans or inspections provide a wealth of information to firefighters when responding to an incident. When firefighters respond to an incident, the pre-fire plan information could alert them to any hazards or possible unsafe conditions that they could be exposed to.

RECOMMENDATION #6 THE DEPARTMENT SHOULD ENSURE THAT THE INCIDENT COMMANDER LOCATE AND CONSULT PLANS DURING EVERY INCIDENT WHERE THERE IS A FIRE.

Discussion: As stated above, pre-fire plans can provide a wealth of information for all responding members. The incident commander should utilize this important resource while developing strategies. In *Fire Command*, Brunnacini writes: "Remember, pre-fire planning

arms the FGC (fire ground commander) with facts that are impossible to acquire under fire conditions.” During the incident in question, pre-fire plans were not utilized.

The Administration should continue in its efforts to obtain funding for an incident command aide with each district chief to ensure that that function is maintained. Until that event occurs, district chiefs should appoint a member who is available to assist with overall command duties. These persons are typically engineer/operators who are not operating a pump and are available to assist the incident commander.

RECOMMENDATION #7: THE DEPARTMENT SHOULD CONSIDER REQUIRING COMPANIES RESPONDING TO WORKING HIGHRISE FIRES TO CHANGE FROM 30 MINUTE AIR BOTTLES TO ONE-HOUR BOTTLES. AIR BOTTLE TANKS SHOULD BE MAINTAINED AT A LEVEL OF AT LEAST 4000 PSI.

Discussion: Highrise fires can place the responding companies in an environment in which members must travel a great distance to arrive at a safe refuge. As conditions worsen, companies often must depend on air from their air bottles both on the fire floor and in the stairway as they enter and leave the area. This creates a great demand on the volume of air from a 30-minute air bottle. The low-pressure alarm should sound at 50% not at 25% to give crews a chance to escape.

Once the Four Leaf Tower fire intensified, members reported the need to plug in their regulators on the second floor as they traveled up the stairs to the fifth floor - - the fire floor. Most of the apparatus on the fire ground were not equipped with one hour bottles which were not a Department requirement. Nevertheless, the companies that were equipped with

such bottles did not switch to them. They were focused on the fire visible upon arrival. Although hindsight is 20/20, most members interviewed wished that they had taken the time to replace their 30-minute bottles with a one-hour bottle. Providing all companies with one-hour bottles and requiring these companies to change out their bottles to the one-hour bottle in a highrise fire would avoid this decision in the future.

Of course user exertion affects the service time of Self-Contained Breathing Apparatus - SCBA. Nevertheless, there are other factors which can affect service time. The *National Fire Protection Association 1981, Standard on Open-Circuit Self-Contained Breathing Apparatus for Fire Service, 1997 Edition*, cites other factors that may affect SCBA service times at A-2-1.1.2. They are: (a) physical condition of the user; (b) emotional condition of the user; (c) the user's degree of training or experience; (d) whether the cylinder is fully charged at the beginning of use; (e) the face piece fit; (f) use in a pressurized tunnel or caisson; (g) the condition of the SCBA; and (h) the SCBA effective dead air space.

NIOSH tested Captain Jahnke's air pack; it passed every test except the "low air alarm test." The test confirmed that the low air alert activated between twenty-three percent and twenty-seven percent of the service life of the air bottle. The standard for this alarm to go off is between 1035 and 1215 psig. The alarm actually went off at 1245 psig which means that the alarm went off 30 psig too soon. Additional residual air would have been available once the warning was activated. In essence, the air bottle did not contribute to this incident. The premature activation of its alarm gave Captain Jahnke an early warning of his situation.

RECOMMENDATION #8: THE DEPARTMENT MUST ENSURE THAT FIRE COMPANIES EQUIPPED WITH THERMAL IMAGER CAMERAS CARRY THESE UNITS WITH THEM ON ALL FIRE CALLS.

Discussion: A thermal imager can be an exceptional tool for firefighters who are inside a building that is on fire. It can be used to quickly locate the seat of a fire in situations where visibility is a problem. A thermal imager can be used to search for fire victims, keep an attack team together and find the optimal path to safety. Because of the importance of this tool, additional training and guidelines must be developed to ensure the proper use of this tool on all fire incidents. Additional training must reiterate the importance of carrying and utilizing this tool on every fire incident. A contributory factor to the incident in question was the failure to have a thermal imager on the fire floor. It was available. It was simply forgotten. A subsequent attempt to retrieve the thermal imager was unsuccessful. The City of Houston was able to buy forty-six of these thermal imager cameras after the McDonald's fire. The long-term goal is to purchase additional cameras for each engine company. It is highly unlikely that firefighters would have had trouble locating an exit or locating a downed firefighter if all crews were equipped with imagers. This is the second firefighter incident in two years in which an imager may have saved the lives of Department firefighters. Two lives may have been saved at the McDonald's fire; one life may have been saved at the incident in question.

RECOMMENDATION #9: THE DEPARTMENT SHOULD DEVELOP A SYSTEM THAT TRACKS SUBSTANTIAL CHANGES IN THE WIND AND WEATHER AND ADVISES MEMBERS IN THE FIELD OF SUCH CHANGES.

Discussion: Weather conditions can be a significant factor when formulating tactics or strategies to control an emergency event. Sudden changes in wind direction or velocity can quickly exacerbate conditions on the fire ground. Fire departments that are engaged in fighting forest fires rely upon up-to-the-minute weather reports to help protect their personnel in the field. The weather report for the date in question showed that winds shifted to the north after a line of thunderstorms hit the Houston area between 3:00 and 4:00 a.m. There were diminishing winds after 4:00 a.m. The winds increased again after 5:00 a.m. At Hull Field in Sugarland, the winds increased from eleven knots at 4:53 a.m. to nineteen knots at 5:11 a.m. This was approximately the same time when the wind exacerbated the conditions on the fire ground at the Four Leaf Towers.

RECOMMENDATION #10: THE DEPARTMENT SHOULD CONTINUE TO COMPLY WITH THE DISCRETIONARY STANDARD OF THE NFPA WHICH RECOMMENDS A MINIMUM OF FOUR FIREFIGHTERS ON ENGINE AND LADDER COMPANIES.

Discussion: The NFPA recommends a minimum of four firefighters on each engine and ladder company responding to a fire. See *National Fire Protection Association Codes and Standards*, Appendix A-6-4.1. This standard is discretionary and is not required by Texas or federal law. Nevertheless, the Department will continue to comply with this standard.

At A-6-4.4, the NFPA Appendix also states:

The assembling of four members for the initial fire attack can be accomplished in many ways. The fire department should determine the manner in which they plan to assemble members in their response plan. The four members assembled for the initial firefighting operations can include an

officer, chief officer or **any combination of members arriving separately at the incident.** [Emphasis added.]

At the incident in question, the initial attack team consisted of two members from E-2 and L-28. The four members of E-3 were assigned as backup for the fire floor. A total of eight members were assigned for the initial attack. At the time of the first call for help, there were fifty-five firefighters on the fire ground. The number of firefighters available for initial attack was not a factor. Communication or “miscommunication” affected the utilization of firefighters during the incident in question.

RECOMMENDATION #11: THE DEPARTMENT SHOULD ENSURE THAT TAGLINES ARE USED IN HIGHRISES OR LARGE STRUCTURES BEFORE VISIBILITY BECOMES A FACTOR.

Discussion: Taglines can be a useful tool to allow firefighters a reliable link to a safe egress from the fire area. Unlike hose lines that may kink or get entangled with hose links coming from a different direction, taglines can be an easy to follow guide to the exit. During the incident in question, the hose looped and traveled in several directions which caused confusion as to where the exit was located. The hose ended at a wall hose cabinet that was about ten feet away from the stairway door. A tagline can be used to overcome these deficiencies. When tied off to the exit door, the tagline becomes an easy tool to find your way to the exit no matter how bad conditions may become in the building.

RECOMMENDATION #12: WHEN PERSONNEL CHANGES OCCUR ON THE FIRE GROUND, THE DEPARTMENT SHOULD MAKE CERTAIN THAT ALL PERSONNEL ARE BRIEFED AS TO THE PROCEDURES TO BE FOLLOWED AND WHAT THEIR SPECIFIC DUTIES ARE.

Discussion: At the fire ground, attack teams may be formed by adding members from different stations. Although most officers and firefighters have completed the same training, procedures and operations can vary according to personnel, shift, or station crews. Briefing sessions can eliminate confusion and any ambiguities as to roles, duties, and responsibilities. They should also help prevent crew fragmentation which was a problem at the incident in question.

RECOMMENDATION #13: THE HOUSTON FIRE DEPARTMENT SHOULD ENSURE THAT 2_ INCH HOSE AND A SMOOTH BORE NOZZLE ARE TAKEN AND USED IN ALL HIGHRISE FIRES.

Discussion: Standpipe systems with PRV systems are typically set between 65 and 100 psi. This range of pressure is insufficient for today's smaller hose with automatic fog nozzles. Although many highrise kits are fitted with low-pressure fog nozzles that will work at these lower pressures, it is still advisable to have this larger diameter hose to produce more gallons per minute of water to battle the blaze. The reduced mobility encountered while using 2_ inch hose, is more than compensated by the increased water flow. The difference in weight between 150 feet of 2 _ inch hose with a nozzle and 150 feet of 1_ inch hose with a nozzle is thirty-four pounds. It is imperative that the highrise survey be reviewed. If the survey shows a standard pressure greater than 150 psi in the building's standpipe system, use of the 2 _ inch hose is precluded. Buildings with pressure reducers

should be identified and labeled. Removal or adjustable reducers should be indicated on the pre-fire plan. According to the highrise survey checklist from District 28, the building was equipped with PRV's with a system pressure of 134 psi. on the fifth floor of the west tower. E-2 connected 1_ hose to the hose cabinet on the fire floor that did not produce the needed volume of water to make an effective attack on this fire.

RECOMMENDATION #14 THE DEPARTMENT SHOULD DEVELOP GUIDELINES THAT MORE CLEARLY DEFINE THE RESPONSIBILITIES OF THE SAFETY OFFICER.

Discussion: The responsibilities and duties of the safety officer are not clearly defined or stated. The safety officer is responsible for monitoring the fire scene for unsafe acts and correcting unsafe behavior. The role is broadly defined. Specific written guidelines are needed to show how the safety officer can accomplish these objectives. Any ambiguity regarding the safety officer role at the fire scene must be eliminated.

RECOMMENDATION #15: THE DEPARTMENT SHOULD ADOPT A WRITTEN GUIDELINE THAT STATES THE CRITERIA USED IN THE DECISION TO MAKE A "MAY-DAY" DECLARATION.

Discussion: Firefighters have not been given sufficient parameters as to when a MAY-DAY should be called. In "MAYDAY-MAYDAY-MAYDAY-DO FIREFIGHTERS KNOW WHEN TO CALL IT?," Burton A. Clark writes: "We have almost completely ignored the most important first step, getting the firefighters to recognize they are in trouble and need to get

help, to call MAYDAY.” Specific guidelines will probably make firefighters less hesitant to make a MAY-DAY call.

RECOMMENDATION #16: THE DEPARTMENT SHOULD ESTABLISH GUIDELINES THAT REDUCE “DUTY AMBIGUITY” WHICH MAY OCCUR AFTER A MAY-DAY DECLARATION HAS BEEN MADE.

Discussion: Firefighters who are assigned to rescue a distressed firefighter must stay focused on that task. On some occasions, these firefighters encounter civilians who are in need of help while responding to a MAY-DAY call. This occurred during the incident in question. Crews assigned to the rescue of the lost firefighter were hampered or delayed by their attempts to help civilians. A focused and quick response to a MAY-DAY call is necessary if a favorable outcome is to be obtained. When assigned units encounter civilians in need of help, they should immediately inform the incident commander about these civilians. They should confirm that help is on the way; they should tell the civilians that help is forthcoming. Immediately they should proceed with their assignment.

RECOMMENDATION #17: THE DEPARTMENT’S BASIC TRAINING REGARDING PROTECTION OF BUILDING OPENINGS DURING A FIRE SHOULD BE REINFORCED.

Discussion: Firefighters are taught in basic training that areas that are not yet affected by heat and smoke should be protected by shutting doors leading to the unaffected areas. Stairwells and doors on the fire floor must remain shut unless use of the stairway standpipe system is necessary. Civilians and firefighters utilize the stairwell during a fire. If heat and smoke from affected areas are allowed to bellow into stairwells and other unaffected areas, fire suppression and rescue become more difficult. A crucial factor in the Four Leaf Towers

incident was the failure to protect the stairwell and hallways from smoke and heat bellowing from the seat of the fire in apartment fifty-two. The door to the apartment should have been shut after the initial attack team was unsuccessful in extinguishing the fire. The conditions on the fire floor were exacerbated by the heat and smoke bellowing out of that apartment.

RECOMMENDATION #18 THE DEPARTMENT SHOULD ESTABLISH TRAINING FOR INCIDENT COMMAND AND HIGHRISE FIREFIGHTING FOR ALL MEMBERS OF THE DEPARTMENT ASSIGNED TO EMERGENCY OPERATIONS.

Discussion: Training should be established to allow members hands-on evolutions covering incident command and highrise firefighting. This training will come in the form of continuing education classes, district training classes, quarterly in-service drills, and multi-company drills. Through the cooperation of the private sector, there will be some training drills held in occupied highrise buildings. The goal of these training sessions will be to familiarize our members with the concepts of incident command and highrise firefighting under safe conditions. The Department should contemplate the creation of an incident command training center where computer simulation equipment can be utilized to prepare the incident commander for the responsibilities concomitant to controlling the scene of an emergency. District chiefs, district training officers, and station officers must be encouraged to effectively utilize their time while on duty. Firefighting requires significant training time to keep skills at high levels. The Jahnke Training Facility is currently too small to provide adequate training for all of the Department's members.

The Administration has made great strides in improving training. It has instituted the "Saving Our Own" program, engineer/operator training, district training officer courses, a professional driver course, and multi-company drills. The sheer size of the Department

dictates that crucial training be dispersed throughout the city rather than at one location.

Therefore, deputy chiefs, district chiefs, district training officers, and station officers are crucial to the Department's efforts to improve training at all levels. Every officer must devote enough time for the training of the members they command.

The Administration established a minimum training requirement of 20-hours to be met each month. The officers at the district and station level know the strengths and weaknesses of members under their command. The officer may need to add additional training to get all members to appropriate competency levels. It can be challenging to accomplish all these training needs and still attend to emergency responses, station and apparatus maintenance, fitness workouts, community service initiatives, and other station duties in the average nine 24-hour work shifts each month. Officers must be very diligent to manage their time effectively. Air-pack drills, highrise and other target hazard simulations, strategy and tactics, hose evolutions, pump operations, pre-fire planning, and site visits can sufficiently be done at the fire station level. Officers should consider training on evenings and weekends. District chiefs and captains play a critical role in the training of the personnel under their command. It is incumbent upon these officers to play the primary role in improving the skills of the firefighters under their command.

RECOMMENDATION #19: THE DEPARTMENT SHOULD ASSESS THE HIGHRISE COMMUNICATION NEEDS TO DETERMINE IF THERE IS A BETTER COMMUNICATION MODEL THAT CAN BE USED DURING INCIDENTS INVOLVING HIGHRISE FIRES.

Discussion: Although each firefighter at the scene has a radio for communication, highrise firefighting continues to tax the communication process of the Department. Part of the problem lies in the sheer number of firefighters competing for air-time on the radios. Many messages become victim to competing messages because of the phenomenon known as being “walked on.” Training sessions in the proper use of radio equipment must be conducted for all members. The Federal Emergency Management Agency has begun to work on the problems associated with communications at the scene of major emergencies.

A study was begun following the events of September eleventh. The study will review inter-agency communication problems at large-scale emergency locations. Perhaps this review of emergency communication problems will help to discover some solutions for the communication problems so often encountered at the scene of an emergency. The Department should form a communication committee to seek opportunities to improve our approach to communications at highrise fires and other emergencies.

The Department should consider allowing dispatchers more leeway in their ability to reinforce the resources on the fire ground. In the Four Leaf Towers fire, the dispatcher pulled a third alarm from the dispatch console upon hearing a MAY-DAY call go out. This helped the incident commander who was too busy assigning companies to call for the third alarm. Early in the fire, however, the dispatcher had confirmation that the Four Leaf Towers had a fire alarm on the fifth floor. If the dispatch protocol had allowed him to pull

the second alarm immediately upon being advised that fire was showing, the second alarm companies could have been dispatched prior to the first unit's arrival at the fire.

RECOMMENDATION #20 THE DEPARTMENT SHOULD CONTINUE TO IMPROVE ITS COMMUNICATION DIVISION.

Discussion: The Department average for call processing is one hundred twenty-four seconds. In essence, it takes one hundred twenty-four seconds from the time that the call comes in before the first apparatus is dispatched. This is remarkable when one considers the fact that our dispatchers process over eight hundred calls per day. Nevertheless, the Department should consider the use of fire tac-dispatchers to reduce communication between fire companies and dispatch. This would facilitate faster dispatches to emergencies.

Currently, the Houston Fire Department is in the process of implementing EAS - - Emergency Alerting System. The system is more efficient and effective than our current microwave system. The system has a computer-generated voice for dispatching emergency incidents and also produces a printed copy of the emergency incident. An attachment to that process is the mobile data terminal that will be installed in the apparatus. This will produce updated information directly to the apparatus of the emergency incident. Upon completion of the new dispatch center, the personnel will be reconfigured to facilitate three tac-dispatchers at one time.

RECOMMENDATION #21: THE DEPARTMENT SHOULD INITIATE TRAINING IN ADVANCED SELF CONTAINED BREATHING APPARATUS --SCBA-- TECHNIQUES.

Discussion: Training exercises on advanced SCBA techniques should be implemented for all members of the Houston Fire Department. These techniques should include controlled breathing techniques, blindfolded air bottle change out, and changing out of air bottles without removal of facemask or regulator. Controlled breathing techniques help one to regulate the amount of air that one is using through mind control. Learning to relax and stay calm can help to conserve air. The blindfolded air bottle change out simulates replacing an air bottle in an environment where the visibility is zero. This evolution and changing out an air bottle without removal of the facemask and regulator truly tests one's ability to adapt and overcome in less than ideal conditions. Training in such life saving techniques can be done at the fire station.

RECOMMENDATION #22: THE DEPARTMENT SHOULD CONSIDER IMPLEMENTING A CREW RESOURCE MANAGEMENT PROGRAM.

Discussion: Firefighter training has traditionally been focused on the behavior of fire and the tactical operation of equipment. Crew resource management is a management tool that was first utilized in the airline industry. This concept recognizes that training in several disciplines can lower the risk of repeated mistakes in highly stressful situations. Now there are initiatives to apply this concept to firefighting. In the fire service context, crew resource management would entail training in the principles of human error, communications, decision-making, and accident prevention in highly stressful situations. Additional training would include situational awareness, leadership, followership, and after-incident review.

The Department could certainly benefit from any regimen that lowers the risk of repeated mistakes.

RECOMMENDATION #23: EMS PERSONNEL WHO ARE DISPATCHED TO MULTI-ALARM FIRES SHOULD BE POSITIONED IN AREAS THAT ARE CONSPICUOUS AND FACILITATE TREATMENT OF VICTIMS.

Discussion: The Department's EMS must be ready to treat the injured as they come out or are carried out of the building. EMS units should be positioned so that they are visible from the exits to the building and readily accessible.

RECOMMENDATION #24: THE DEPARTMENT SHOULD EXPAND THE CURRENT PROGRAM FOR THE PHYSICAL FITNESS OF OUR MEMBERS.

Discussion: The rigors of a highrise fire quickly show the need for our members to be in great physical shape. Climbing stairs and carrying equipment, while wearing full protective gear, can take its toll on even the firefighter in the best of physical shape. The fire ground is no place for a firefighter who is out of shape. The majority of our firefighter deaths are due to heart attacks. We can no longer sit back and allow this to continue in the fire service. The time has come for our firefighters to begin an effective physical fitness program. The current physical fitness program has made improvements, but more needs to be done. **Firefighters need to take personal responsibility for their own fitness.**

In the Four Leaf Towers fire, our firefighters were forced to push themselves beyond their

normal fitness range. Carrying heavy equipment, climbing stairs, and extending the range of air bottles, require physical fitness.

RECOMMENDATION #25: THE FIRE DEPARTMENT SHOULD CONTINUE TO EVALUATE NEW TECHNOLOGY IN ORDER TO REDUCE THE RISKS INHERENT IN FIREFIGHTING.

Discussion: New products are continually being produced to reduce the risks of firefighting.

Communication devices such as voice amplifiers and facemask speakers may help with radio communications during a highrise fire. Light beacons and hose markings may help a firefighter move to safety. A flashing light on an injured firefighter may help locate him.

The Joint Labor and Management Safety Committee must continue to review new technology and make recommendations to the Administration.

RECOMMENDATIONS #26: THE DEPARTMENT SHOULD RECOMMEND TO THE CITY'S ADMINISTRATION THAT THE CITY'S BUILDING CODES BE AMENDED TO REQUIRE OLDER HIGHRISES TO BE RETROFITTED WITH WATER SPRINKLER SYSTEMS.

Discussion: The Department recommends that older highrise buildings be retrofitted with sprinkler systems. The Department should recommend to the City's Administration that the building codes be amended to require such retrofitting. According to the Houston Fire Marshal's Office, there are over three hundred fifty highrise buildings in Houston without sprinkler systems. There is the potential for future tragedies. The NFPA's *Fire Protection Handbook, Sixteenth Edition* at page 18-3 states: "The NFPA has no record of a multiple death fire (a fire which kills three or more people) in a completely sprinklered building where

the system was operating properly, except where an explosion occurred or flash fire killed victims prior to the systems operation.”

RECOMMENDATION #27: THE INCIDENT COMMAND AT A HIGHRISE FIRE MUST MAKE CONFIRMATION OF THE FIRE FLOOR BEFORE ATTACK TEAMS ARE DEPLOYED.

Discussion: The initial attack team should determine and confirm the location of the fire floor. The team should then transmit the location to the incident commander. No officer should deploy additional firefighters to a purported fire floor until that officer has received confirmation of the fire floor from the incident commander. During the incident in question, there was confusion as to whether the fire floor was the third floor or the fifth floor. This confusion was not caused by a shortage of manpower on the fire ground. A reason E-3 was delayed in getting to the fire floor is that he was told that the fire was on the third floor instead of the fifth floor. The incident command must confirm the location of the fire floor before additional firefighters are deployed.

CONCLUSION

As stated above, the objective of this report is to help improve the Department. This document is a tool for learning. Any attempt to attribute the cause of this incident to any single factor is both biased and inaccurate. Several factors contributed to the incident in question. The highrise building in question was not completely sprinklered. This was certainly a factor. Nevertheless, the Department did not and cannot control this factor. Of course, the Department cannot control the wind. It will attempt to become better apprised of wind conditions in the future. The Department, however, can and must control the other contributing factors. The failure to adhere to the Department's guidelines will be controlled. The failure to follow basic firefighting principles will be controlled. Failure to focus on assigned tasks will be corrected. Communication guidelines will be reinforced. The Department has learned from this incident. It is now time to move forward.